

序号	报告编号	发布日期	结论	影像资料
1	GX-B1598/24-6-25043	2025/5/9	实测钢丝绳有效截面积损失百分比最大为0.75%，小于5%为正常	
2	GX-B1598/24-6-25044	2025/5/9	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。	
3	GX-B1598/24-6-25045	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.09%，小于5%为正常。	

4	GX-B1598/24-6-25046	2025/5/9	实测钢丝绳有效截面积损失百分比最大为0.97%，小于5%为正常。	
5	GX-B1598/24-6-25047	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.12%，小于5%为正常。	
6	GX-B1598/24-6-25048	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.17%，小于5%为正常	

7	GX-B1598/24-6-25049	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.18%，小于5%为正常	
8	GX-B1598/24-6-25050	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常	
9	GX-B1598/24-6-25051	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。	

10	GX-B1598/24-6-25052	2025/5/9	实测钢丝绳有效截面积损失百分比最大为1.51%，小于5%为正常。	
11	GX-B1451/20-6-25544~25551	2025/5/9	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
12	GX-B1427/21-6-25027	2025/5/9	符合标准要求。	

13	GX-B1427/21-6-25028	2025/5/9	符合标准要求。		 A worker wearing a red hard hat, safety glasses, and a grey uniform is working on a metal component. They are using a blue tool. The date stamp in the bottom right corner of the image is 2025 05 09.
14	GX-B1427/21-6-25029	2025/5/9	符合标准要求。		 A worker wearing a red hard hat, safety glasses, and a grey uniform is working on a metal component. They are using a blue tool. The date stamp in the bottom right corner of the image is 2025 05 09.
15	GX-B1310/21-6-25125	2025/5/9	符合标准要求		 A worker wearing a red hard hat, safety glasses, and a grey uniform is working on a metal component. They are using a blue tool. The date stamp in the bottom right corner of the image is 2025 05 09.

16	GX-B1310/21-6-25126	2025/5/9	符合标准要求		
17	GX-B1310/21-6-25127	2025/5/9	符合标准要求		