


序号	报告编号	发布日期	结论	影像资料
8	GX-B1328/20-5-24076	2024/5/10	本次共检绝缘手套8只，8只绝缘手套合格。	
9	GX-B1328/20-5-24077	2024/5/10	本次共检绝缘鞋8只，8只绝缘鞋合格。	
10	GX-B1328/20-5-24078	2024/5/10	本次共检验电器4套，4套验电器合格。	

11	GX-B1328/20-5-24079	2024/5/10	本次共检携带式接地和接地短路装置2套，2套携带式接地和接地短路装置合格。	
12	GX-B1328/20-5-24080	2024/5/10	本次共检绝缘杆2支，2支绝缘杆合格。	
13	GX-B1559/22-5-24001	2024/5/10	所检项目合格。	

14	GX-B1559/22-5-24002	2024/5/10	所检项目合格。	 A man in a black jacket and glasses stands next to a yellow piece of heavy machinery, holding a clipboard. A red date stamp '2024/05/25' is in the bottom right corner.
15	GX-B1559/22-5-24003	2024/5/10	所检项目合格。	 A man in a black jacket and glasses stands next to a yellow piece of heavy machinery, holding a clipboard. A red date stamp '2024/05/25' is in the bottom right corner.
16	GX-B1328/20-5-24074	2024/5/10	本次共检绝缘手套4只，4只绝缘手套合格。	 A yellow metal stand holds four yellow insulation gloves. A red date stamp '2024/04/12' is in the bottom right corner.


17	GX-B1328/20-5-24075	2024/5/10	本次共检绝缘鞋4只，4只绝缘鞋合格。	
18	GX-B1328/20-5-24065	2024/5/10	本次共检验电器2套，2套验电器合格。	
19	GX-B1328/20-5-24066	2024/5/10	本次共检便携式接地和接地短路装置2套，2套便携式接地和接地短路装置合格。	

20	GX-B1428/21-5-24006	2024/5/10	无缺陷迹痕显示。	
21	GX-B1428/21-5-24007	2024/5/10	无缺陷迹痕显示。	
22	GX-B1310/21-5-24095	2024/5/10	符合标准要求。	

23	GX-B1310/21-5-24096	2024/5/10	符合标准要求。		
24	GX-B1328/20-5-24060	2024. 5. 13	本次共检验电器37套，37套验电器合格。		
25	GX-B1328/20-5-24061	2024. 5. 13	本次共检携带式接地和接地短路装置37套，37套携带式接地和接地短路装置合格。		

26	GX-B1499/23-5-24035	2024/5/15	所检项目合格。			
27	GX-B1499/23-5-24036	2024/5/15	所检项目合格。			
28	GX-B1499/23-5-24037	2024/5/15	所检项目合格。			

29	GX-B1499/23-5-24038	2024/5/15	除吨水百米电耗超限外， 其余所检项目合格。			
30	GX-B1499/23-5-24039	2024/5/15	除吨水百米电耗超限外， 其余所检项目合格。			
31	GX-B1499/23-5-24040	2024/5/15	除吨水百米电耗超限外， 其余所检项目合格。			

32	GX-B1499/23-5-24041	2024/5/16	所检项目合格。		 A worker wearing a red helmet and blue uniform is inspecting a large blue pipe in a tunnel. The worker is holding a device and looking at it. The date 2024/04/16 is visible in the bottom right corner of the image.	
33	GX-B1499/23-5-24042	2024/5/16	所检项目合格。		 A worker wearing a red helmet and blue uniform is inspecting a large blue pipe in a tunnel. The worker is holding a device and looking at it. The date 2024/04/16 is visible in the bottom right corner of the image.	
34	GX-B1499/23-5-24043	2024/5/15	所检项目合格。		 A worker wearing a red helmet and blue uniform is inspecting a large blue pipe in a tunnel. The worker is holding a device and looking at it. The date 2024/04/14 is visible in the bottom right corner of the image.	

35	GX-B1499/23-5-24044	2024/5/15	所检项目合格。			
36	GX-B1499/23-5-24045	2024/5/15	所检项目合格。			
37	GX-B1499/23-5-24046	2024/5/15	所检项目合格。			

38	GX-B1499/23-5-24047	2024/5/15	所检项目合格。			
39	GX-B1499/23-5-24048	2024/5/15	所检项目合格。			
40	GX-B1499/23-5-24049	2024/5/15	所检项目合格。			

41	GX-B1499/23-5-24050	2024/5/15	所检项目合格。		 2024/04/19	
42	GX-B1499/23-5-24051	2024/5/15	所检项目合格。		 2024/04/19	
43	GX-B1499/23-5-24052	2024/5/15	所检项目合格。		 2024/04/19	

44	GX-B1499/23-5-24053	2024/5/15	所检项目合格。	
45	GX-B1308/23-5-24008	2024/5/15	综合判定：合格。	
46	GX-B1308/23-5-24009	2024/5/15	综合判定：合格。	

47	GX-B1308/23-5-24010	2024/5/15	综合判定：合格。			
----	---------------------	-----------	----------	--	---	--