


序号	报告编号	发布日期	结论	影像资料
1	GX-B1412/22-B-24014	2024.6.3	所检项目合格	
2	GX-B1601/22-B-240288~240290	2024.6.3	所检项目合格	
3	GX-B1568/22-B-240206	2024.6.3	所检项目合格	

4	GX-B1568/22-B-240201~240205	2024.6.3	所检项目合格	
5	GX-B1601/22-B-240323~240325	2024.6.4	所检项目合格	
6	GX-B1595/22-B-240082	2024.6.4	所检项目合格	

7	GX-B1374/22-B-240369~240375	2024年6月4日	所检项目合格	 A technician in a grey lab coat with the '中检公信' logo is working on a piece of equipment inside a laboratory fume hood. A woman in a grey lab coat is standing next to him, observing. The date '2024.5.23' is visible in the bottom right corner of the photo.
8	GX-B1374/22-B-240351~240360	2024年6月4日	所检项目合格	 Three technicians in grey lab coats are working in a laboratory. One technician is operating a piece of equipment, while the other two are observing. The date '2024.5.12' is visible in the bottom right corner of the photo.
9	GX-B1593/21-B-24120~24121	2024年6月4日	所检项目合格	 Two technicians in grey lab coats are working in a laboratory. One technician is operating a piece of equipment, while the other is observing. The date '2024.5.13' is visible in the bottom right corner of the photo.

10	GX-B1592/21-B-24054	2024年6月4日	所检项目合格	 A photograph showing two male technicians in a laboratory. One technician is standing and looking at a piece of equipment on a table, while the other is leaning over the table, possibly adjusting or operating it. The equipment appears to be a testing device with various cables and components. A timestamp '2024.5.13' is visible in the bottom right corner of the image.
11	GX-B1603/22-B-240154~240156	2024.6.5	所检项目合格	 A photograph showing two technicians in a laboratory. One technician is seated at a control panel with a large screen, while the other is standing next to a large, cylindrical industrial machine, possibly a furnace or a reactor, and appears to be adjusting or inspecting it. A timestamp '2024.6.3' is visible in the bottom right corner of the image.
12	GX-B1531/20-B-241095~241144	2024.6.5	所检项目合格	 A photograph showing two technicians in a laboratory. They are both looking at a piece of equipment on a table. One technician is holding a yellow object, possibly a sample or a component, and the other is looking at it. The equipment on the table has various cables and components. A timestamp '2024.5.28' is visible in the bottom right corner of the image.

13	GX-B1531/20-B-240945~240994	2024.6.5	所检项目合格	
14	GX-B1531/20-B-240995~241044	2024.6.5	所检项目合格	
15	GX-B1531/20-B-241045~241094	2024.6.5	所检项目合格	

16	GX-B1603/22-B-240157~240158	2024年6月5日	所检项目合格	
17	GX-B1603/22-B-240159~240163	2024年6月5日	所检项目合格	

18	GX-B1593/21-B-24192~24198	2024年6月6日	所检项目合格	
----	---------------------------	-----------	--------	---

