

序号	报告编号	发布日期	结论	影像资料
13	GX-B1340/23-8-24043	2024. 8. 16	1#在用主要通风机系统合格。 。	 A photograph showing two workers in dark uniforms and red hard hats standing next to a large, dark-colored industrial fan unit outdoors. The ground is gravel, and there are some pipes and structures in the background. A timestamp '2024.7.31' is visible in the bottom right corner of the image.
14	GX-B1340/23-8-24044	2024. 8. 16	2#在用主要通风机系统合格。 。	 A photograph showing three workers in dark uniforms and red hard hats standing in an industrial area. They appear to be looking at something together. The background shows concrete walls and some equipment. A timestamp '2024.7.31' is visible in the bottom right corner of the image.
15	GX-B1341/24-8-24033	2024. 8. 13	综合判断：合格	 A photograph showing two workers in dark uniforms and red hard hats in a dark, underground tunnel. They are looking at a document or piece of equipment. The tunnel walls are rocky and there are some pipes and equipment visible. A timestamp '2024-07-19' is visible in the bottom right corner of the image.

16	GX-B1341/24-8-24034	2024. 8. 13	综合判断：合格	
17	GX-B1343/21-8-23014	2024. 8. 13	矿井通风阻力：北风井通风系统1112.3 Pa；南风井通风系统909.2 Pa。	
18	GX-B1347/21-8-23014	2024. 8. 13	综合指标：88.8%，大于72%，合格。	

19	GX-B1341/24-8-24032	2024. 8. 13	综合判断：合格	
20	GX-B1343/21-8-24013	2024. 8. 13	<ol style="list-style-type: none"> 1. 矿井总风量：893.3 m³/min； 2. 主通风机风量：1209.6 m³/min； 3. 矿井通风阻力：236.2 Pa； 4. 风量（风速）合格率：100%，大于65%，合格； 5. 风质合格率：100%，大于90%，合格； 6. 作业环境空气质量合格率：100%，大于60%，合格； 7. 矿井有效风量率：67.9%，大于60%，合格； 8. 风机全压效率：86.0%，大于70%，合格； 9. 风量供需比：1.54，符合$1.32 \leq \beta \leq 1.67$要求，合格； 10. 综合指标：91.4%，大于72%，合格。 	