

序号	报告编号	发布日期	结论	影像资料
345	GX-B1363/22-A-24609	2024/11/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1363/22-A-24610	2024/11/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1363/22-A-24636	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1363/22-A-24668	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1364/22-A-241343	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1364/22-A-241312	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
351	GX-B1364/22-A-241313	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
352	GX-B1364/22-A-241314	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
353	GX-B1364/22-A-241315	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
354	GX-B1364/22-A-241316	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
355	GX-B1364/22-A-241317	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
356	GX-B1363/22-A-24637	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
357	GX-B1363/22-A-24631	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
358	GX-B1363/22-A-24632	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
359	GX-B1363/22-A-24625	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
360	GX-B1363/22-A-24634	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
361	GX-B1509/20-A-24036	2024/11/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
362	GX-B1364/22-A-241345	2024/11/28	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
363	GX-B1364/22-A-241346	2024/11/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
364	GX-B1364/22-A-241347	2024/11/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
365	GX-B1364/22-A-241348	2024/11/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
366	GX-B1364/22-A-241349	2024/11/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
367	GX-B1364/22-A-241350	2024/11/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
368	GX-B1364/22-A-241351	2024/11/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
369	GX-B1368/20-A-24006	2024/11/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
370	GX-B1368/20-A-24007	2024/11/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
371	GX-B1364/22-A-241344	2024/11/28	所检项目合格。	 A photograph showing two technicians in white uniforms with '中检公信' (Zhongjian Gongxin) logos on their backs. They are inspecting a large, black industrial machine with a red door that is open. The machine is situated in a room with white walls and some equipment visible in the background. A date stamp '2024.11.26' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
372	GX-B1364/22-A-241333	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
373	GX-B1364/22-A-241334	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
374	GX-B1364/22-A-241335	2024/11/29	所检项目合格。	 A photograph showing two technicians in white uniforms inspecting a large industrial machine. The technician on the left is seen from the back, wearing a uniform with a logo. The technician on the right is facing the machine, which has a control panel with a screen and various buttons. The machine is dark-colored and stands in a room with white walls. A date stamp '2024.11.22' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
375	GX-B1364/22-A-241336	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
376	GX-B1364/22-A-241337	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
377	GX-B1364/22-A-241341	2024/11/29	成束电线电缆 燃烧试验不合格，其余所检 项目合格。	

序号	报告编号	发布日期	结论	影像资料
378	GX-B1538/22-A-24096	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
379	GX-B1538/22-A-24097	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
380	GX-B1538/22-A-24098	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
381	GX-B1538/22-A-24099	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
382	GX-B1538/22-A-24100	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
383	GX-B1538/22-A-24101	2024/11/29	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
384	GX-B1538/22-A-24102	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
385	GX-B1364/22-A-241342	2024/11/29	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
386	GX-B1363/22-A-24683	2024/11/29	所检项目合格。	 A photograph showing two men in grey work uniforms inspecting a large, rusted industrial furnace or boiler. One man is on the left, wearing yellow gloves and looking into the open door of the furnace. The other man is on the right, also looking into the furnace. The furnace is a large, boxy metal structure with a tall, cylindrical chimney pipe extending from the top. To the left of the furnace is a green plastic trash bin. To the right is a green floor fan. The room has white walls and a window with black frames in the background. A timestamp '2024.11.28' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
387	GX-B1363/22-A-24684	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
388	GX-B1509/20-A-24039	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
389	GX-B1509/20-A-24040	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
390	GX-B1509/20-A-24041	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
391	GX-B1509/20-A-24042	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
392	GX-B1509/20-A-24043	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
393	GX-B1509/20-A-24037	2024/11/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
394	GX-B1509/20-A-24038	2024/11/29	所检项目合格。	