

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-4-24211	2024.12.4	符合标准要求。	 A photograph showing a worker in a red helmet and orange safety gear working in a dark industrial environment. The worker is positioned near some machinery. A red timestamp '2024.11.16' is visible in the bottom right corner of the image.
2	GX-B1310/21-4-24212	2024.12.4	符合标准要求。	 A photograph showing a worker in a red helmet and orange safety gear working in a dark industrial environment. The worker is holding a device or tool. A red timestamp '2024.11.16' is visible in the bottom right corner of the image.
3	GX-B1310/21-4-24213	2024.12.4	符合标准要求。	 A photograph showing a worker in a red helmet and orange safety gear working in a dark industrial environment. The worker is standing next to some equipment. A red timestamp '2024.11.16' is visible in the bottom right corner of the image.

4	GX-B1310/21-4-24214	2024. 12. 4	符合标准要求。	
5	GX-B1310/21-4-24215	2024. 12. 4	符合标准要求。	
6	GX-B1310/21-4-24216	2024. 12. 4	符合标准要求。	

7	GX-B1310/21-4-24217	2024.12.4	符合标准要求。	
---	---------------------	-----------	---------	---