

序号	报告编号	发布日期	结论	影像资料
26	GX-B1424/20-5-24069	2024. 12. 24	依据NB/T 10176-2019单轨吊车 综合判定合格； 依据MT/T 220-1990 尾气所检项 目合格。	
27	GX-B1424/20-5-24070	2024. 12. 24	依据NB/T 10176-2019单轨吊车 综合判定合格； 依据MT/T 220-1990 尾气所检项 目合格。	
28	GX-B1310/21-5-24411	2024. 12. 23	符合标准要求。	

29	GX-B1310/21-5-24412	2024. 12. 24	符合标准要求。	
30	GX-B1310/21-5-24406	2024. 12. 18	符合标准要求。	
31	GX-B1328/20-5-24177	2024/12/26	本次共检验电器10支，10支验电器合格。	

32	GX-B1328/20-5-24178	2024/12/26	本次共检便携式接地和接地短路装置10套，10套便携式接地和接地短路装置合格。	
33	GX-B1328/20-5-24179	2024/12/26	本次共检绝缘杆10支，10支绝缘杆合格。	

34	GX-B1328/20-5-24180	2024. 12. 26	本次共检绝缘手套2只，2只绝缘手套合格。	
35	GX-B1351/21-5-24005~24006	2024. 12. 27	本次共检矿用隔爆型检漏继电器2台, 2台所检项目合格。	
36	GX-B1352/21-5-24013~24014	2024. 12. 27	本次共检矿用防爆低压交流真空馈电开关漏电保护2台, 2台矿用防爆低压交流真空馈电开关漏电所检项目合格。	


37	GX-B1352/21-5-24015~24019	2024. 12. 27	<p>本次共检矿用防爆低压交流真空馈电开关漏电保护5台, 5台矿用防爆低压交流真空馈电开关漏电所检项目合格。</p>	
38	GX-B1352/21-5-24020~24022	2024. 12. 27	<p>本次共检矿用防爆低压交流真空馈电开关漏电保护3台, 3台矿用防爆低压交流真空馈电开关漏电所检项目合格。</p>	
39	GX-B1310/21-5-24409	2024/12/25	<p>符合标准要求。</p>	

40	GX-B1310/21-5-24410	2024/12/25	符合标准要求。	
41	GX-B1428/21-5-24020	2024/12/26	无缺陷迹痕显示。	

42	GX-B1428/21-5-24021	2024/12/26	无缺陷迹痕显示。	
43	GX-B1328/20-5-24173	2024. 12. 30	本次共检绝缘胶垫228个，228个绝缘胶垫合格。	
44	GX-B1328/20-5-24171	2024. 12. 30	本次共检绝缘杆2支，2支绝缘杆合格。	

45	GX-B1328/20-5-24169	2024. 12. 30	本次共检便携式接地和接地短路装置68套，68套便携式接地和接地短路装置合格。	
46	GX-B1328/20-5-24167	2024. 12. 30	本次共检绝缘手套152只，152只绝缘手套合格。	
47	GX-B1328/20-5-24168	2024. 12. 30	本次共检绝缘靴100只，100只绝缘靴合格。	

48	GX-B1328/20-5-24174	2024. 12. 30	本次共检便携式接地和接地短路装置5套，5套便携式接地和接地短路装置合格。	
49	GX-B1328/20-5-24175	2024. 12. 30	本次共检验电器10支，10支验电器合格。	
50	GX-B1328/20-5-24170	2024. 12. 30	本次共检验电器33支，33支验电器合格。	

51	GX-B1427/21-5-24015	2024. 12. 31	符合标准要求。		 A worker wearing a red hard hat, a white jacket, and blue gloves stands in an industrial environment. The worker is positioned next to a blue metal structure, possibly a conveyor belt or a large container. The background shows industrial machinery and a concrete floor. A yellow timestamp '2024/12/15' is visible in the bottom right corner of the image.	
52	GX-B1427/21-5-24016	2024. 12. 31	符合标准要求。		 A worker wearing a red hard hat and a grey jacket is working on a large, dark metal component. The worker is positioned in a narrow, industrial space, possibly a tunnel or a large pipe. The component is dark and has several bolts or fasteners. A yellow timestamp '2024/12/15' is visible in the bottom right corner of the image.	