

序号	报告编号	发布日期	结论	影像资料
1	GX-B1364/22-A-25467	2025/5/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2	GX-B1364/22-A-25466	2025/5/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1538/22-A-25041	2025/5/7	所检项目合格。	 A photograph showing two male technicians in light grey lab coats with the '中检公信' (Zhongjian Gongxin) logo on the back, working in a laboratory. They are standing in front of a large, dark industrial machine, possibly a furnace or a testing chamber. The technician on the left is looking at the machine's control panel, while the one on the right is looking at a computer monitor. A date stamp '2025.04.29' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
4	GX-B1538/22-A-25042	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
5	GX-B1538/22-A-25043	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
6	GX-B1538/22-A-25044	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
7	GX-B1538/22-A-25045	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
8	GX-B1538/22-A-25046	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
9	GX-B1538/22-A-25047	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
10	GX-B1538/22-A-25048	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1538/22-A-25049	2025/5/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
12	GX-B1364/22-A-25468	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1364/22-A-25471	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
14	GX-B1364/22-A-25472	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
15	GX-B1364/22-A-25473	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
16	GX-B1364/22-A-25474	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
17	GX-B1365/25-A-25048	2025/5/8	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
18	GX-B1365/25-A-25049	2025/5/8	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1366/25-A-25050	2025/5/8	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1366/25-A-25051	2025/5/8	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
21	GX-B1363/22-A-25271	2025/5/8	所检项目合格。	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers inspecting a large, rusted industrial machine. The technician on the left is wearing yellow gloves and is looking into the open front panel of the machine. The technician on the right is also looking into the machine. The machine is a large, boxy unit with a vertical pipe on top. In the background, there is a window with a view of green trees outside and a large green floor fan. The date stamp '2025.05.07' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
22	GX-B1363/22-A-25273	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1363/22-A-25267	2025/5/8	所检项目合格。	 A photograph showing two male technicians in light blue work uniforms inspecting a large, rusted industrial metal furnace. The technician on the right is wearing yellow and red safety gloves and is looking at a digital display on the furnace door. The technician on the left is also looking at the furnace. The furnace has several yellow warning labels with black text and symbols. A timestamp '2025.05.05' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
24	GX-B1363/22-A-25268	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1363/22-A-25270	2025/5/8	所检项目合格。	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers inspecting a large, rusted industrial furnace. The furnace has a digital display on its front door and several yellow triangular warning labels. One technician is on the left, looking at the display, while the other is on the right, looking at the furnace's interior. The furnace is situated in a room with a window and a green floor fan in the background. An orange timestamp '2025.05.06' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
26	GX-B1363/22-A-25272	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
27	GX-B1364/22-A-25469	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1364/22-A-25470	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1364/22-A-25475	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1364/22-A-25476	2025/5/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1364/22-A-25477	2025/5/8	所检项目合格。	