

序号	报告编号	发布日期	结论	影像资料
58	GX-B1323/21-1-25111~25119	2025. 5. 12	所检项目合格	
59	GX-B1323/21-1-25120~25123	2025. 5. 12	所检项目合格	


60	GX-B1323/21-1-25124~25129	2025. 5. 12	所检项目合格	 2025.2.25
61	GX-B1323/21-1-25130~25134	2025. 5. 12	所检项目合格	 2025.2.27
62	GX-B1323/21-1-25135~25139	2025. 5. 12	所检项目合格	 2025.3.5


63	GX-B1323/21-1-25140~25143	2025. 5. 12	所检项目合格	
64	GX-B1323/21-1-25144~25151	2025. 5. 12	所检项目合格	
65	GX-B1323/21-1-25152~25156	2025. 5. 12	所检项目合格	

66	GX-B1323/21-1-25157~25164	2025. 5. 12	所检项目合格	 A person wearing glasses and a dark jacket is using a bright handheld light to inspect a piece of machinery. The scene is dark, with the light illuminating the equipment and the person's face. A timestamp "2025.3.15" is visible in the bottom right corner of the image.
67	GX-B1323/21-1-25165~25170	2025. 5. 12	所检项目合格	 A person wearing a red hard hat and dark clothing is working on a piece of machinery. The scene is dark, with a bright light source illuminating the person and the equipment. A timestamp "2025.3.19" is visible in the bottom right corner of the image.
68	GX-B1323/21-1-25171~25174	2025. 5. 12	所检项目合格	 A person wearing a dark jacket and a headlamp is using a handheld light to inspect a piece of machinery. The scene is dark, with the light illuminating the equipment and the person's face. A timestamp "2025.2.27" is visible in the bottom right corner of the image.

69	GX-B1323/21-1-25175~25184	2025. 5. 12	所检项目合格	
70	GX-B1323/21-1-25185~25192	2025. 5. 12	所检项目合格	
71	GX-B1323/21-1-25193~25194	2025. 5. 12	所检项目合格	

72	GX-B1323/21-1-25195~25202	2025. 5. 12	所检项目合格	
73	GX-B1495/20-1-25579~25589	2025. 5. 12	本次共检高压开关设备11台，11台高压开关设备所检项目合格	
74	GX-B1321/20-1-25451~25458	2025. 5. 12	本次共检电力电缆8条，8条电力电缆所检项目合格	

75	GX-B1321/20-1-25459~25468	2025. 5. 12	本次共检电力电缆10条，10条电力电缆所检项目合格		
76	GX-B1321/20-1-25469~25479	2025. 5. 12	本次共检电力电缆11条，11条电力电缆所检项目合格		
77	GX-B1321/20-1-25480~25485	2025. 5. 12	本次共检电力电缆6条，6条电力电缆所检项目合格		

78	GX-B1321/20-1-25486~25491	2025. 5. 12	本次共检电力电缆6条，6条电力电缆所检项目合格	
79	GX-B1321/20-1-25492~25500	2025. 5. 12	本次共检电力电缆9条，9条电力电缆所检项目合格	
80	GX-B1321/20-1-25501~25506	2025. 5. 12	本次共检电力电缆6条，6条电力电缆所检项目合格	

81	GX-B1310/21-1-25112	2025. 5. 12	符合标准要求	
82	GX-B1310/21-1-25113	2025. 5. 12	符合标准要求	
83	GX-B1310/21-1-25114	2025. 5. 12	符合标准要求	

84	GX-B1310/21-1-25116	2025. 5. 12	符合标准要求		
85	GX-B1310/21-1-25117	2025. 5. 12	符合标准要求		
86	GX-B1310/21-1-25118	2025. 5. 12	符合标准要求		

87	GX-B1304/21-1-25006	2025. 5. 12	综合判定：合格	 <p>2025 04 26</p>
88	GX-B1310/21-1-25107	2025. 5. 13	符合标准要求	 <p>2025/04/26</p>
89	GX-B1428/21-1-25107	2025. 5. 13	无缺陷迹痕显示	 <p>2025/04/26</p>

90	GX-B1309/21-1-25020	2025. 5. 14	所检项目合格	
91	GX-B1500/21-1-25076	2025. 5. 14	综合判定：合格	
92	GX-B1500/21-1-25077	2025. 5. 14	综合判定：合格	

93	GX-B1500/21-1-25078	2025. 5. 14	综合判定：合格	
94	GX-B1309/21-1-25021	2025. 5. 14	所检项目合格	
95	GX-B1500/21-1-25079	2025. 5. 14	综合判定：合格	

96	GX-B1500/21-1-25080	2025. 5. 14	综合判定：合格	
97	GX-B1500/21-1-25081	2025. 5. 14	综合判定：合格	
98	GX-B1309/21-1-25022	2025. 5. 14	所检项目合格	

99	GX-B1500/21-1-25082	2025. 5. 14	综合判定：合格	
100	GX-B1500/21-1-25083	2025. 5. 14	综合判定：合格	
101	GX-B1500/21-1-25084	2025. 5. 14	综合判定：合格	

102	GX-B1309/21-1-25017	2025. 5. 14	所检项目合格	
103	GX-B1500/21-1-25064	2025. 5. 14	综合判定：合格	
104	GX-B1500/21-1-25065	2025. 5. 14	综合判定：合格	

105	GX-B1500/21-1-25066	2025. 5. 14	综合判定：合格	
106	GX-B1309/21-1-25024	2025. 5. 14	所检项目合格	
107	GX-B1500/21-1-25089	2025. 5. 14	综合判定：合格	

108	GX-B1500/21-1-25090	2025. 5. 14	综合判定：合格		
109	GX-B1500/21-1-25091	2025. 5. 14	综合判定：合格		
110	GX-B1309/21-1-25024	2025. 5. 14	所检项目合格		

111	GX-B1500/21-1-25089	2025. 5. 14	综合判定：合格	
112	GX-B1500/21-1-25090	2025. 5. 14	综合判定：合格	
113	GX-B1500/21-1-25091	2025. 5. 14	综合判定：合格	

114	GX-B1534/20-1-25016	2025. 5. 14	所检项目合格	 <p>2025/05/02</p>
115	GX-B1534/20-1-25017	2025. 5. 14	所检项目合格	 <p>2025/05/02</p>
116	GX-B1534/20-1-25018	2025. 5. 14	所检项目合格	 <p>2025/05/02</p>

117	GX-B1534/20-1-25019	2025. 5. 14	所检项目合格	
118	GX-B1534/20-1-25020	2025. 5. 14	所检项目合格	
119	GX-B1534/20-1-25021	2025. 5. 14	所检项目合格	

120	GX-B1304/21-1-25005	2025. 5. 14	综合判定：合格	
121	GX-B1451/20-1-251097~251120	2025. 5. 14	<p>本次共检高压开关柜 24台，24台高压开关柜所检 项目合格</p>	
122	GX-B1451/20-1-251121~251139	2025. 5. 14	<p>本次共检高压开关柜 19台，19台高压开关柜所检 项目合格</p>	

123	GX-B1451/20-1-251140~251149	2025. 5. 14	<p>本次共检高压开关柜 10台, 10台高压开关柜所检 项目合格</p>	
124	GX-B1451/20-1-251150~251165	2025. 5. 14	<p>本次共检高压开关柜 16台, 16台高压开关柜所检 项目合格</p>	
125	GX-B1451/20-1-251166~251183	2025. 5. 14	<p>本次共检高压开关柜 18台, 18台高压开关柜所检 项目合格</p>	

126	GX-B1319/21-1-25011~25012	2025. 5. 15	本次共检高压交流断路器2台，2台高压交流断路器所检项目合格	
127	GX-B1312/20-1-25199~25204	2525. 5. 15	本次共检电力变压器6台，6台电力变压器所检项目合格	
128	GX-B1312/20-1-25205~25207	2525. 5. 15	本次共检电力变压器3台，3台电力变压器所检项目合格	

129	GX-B1312/20-1-25208~25209	2025. 5. 15	本次共检电力变压器 2台，2台电力变压器所检 项目合格	
130	GX-B1312/20-1-25210~25212	2025. 5. 15	本次共检电力变压器 3台，3台电力变压器所检 项目合格	
131	GX-B1312/20-1-25213~25216	2025. 5. 15	本次共检电力变压器 4台，4台电力变压器所检 项目合格	

132	GX-B1312/20-1-25217~25221	2025. 5. 15	<p>本次共检电力变压器 5台，5台电力变压器所检 项目合格</p>	
133	GX-B1312/20-1-25222~25223	2025. 5. 15	<p>本次共检电力变压器 2台，2台电力变压器所检 项目合格</p>	
134	GX-B1312/20-1-25224~25230	2025. 5. 15	<p>本次共检电力变压器 7台，7台电力变压器所检 项目合格</p>	

135	GX-B1312/20-1-25231~25233	2025. 5. 15	本次共检电力变压器3台， 3台电力变压器所检项目合格	 <p>2025/3/15</p>
136	GX-B1312/20-1-25234~25237	2025. 5. 15	本次共检电力变压器 4台，4台电力变压器所检 项目合格	 <p>2025/3/16</p>
137	GX-B1312/20-1-25238~25241	2025. 5. 15	本次共检电力变压器4台， 4台电力变压器所检项目合格	 <p>2025/3/17</p>

138	GX-B1312/20-1-25242~25248	2025. 5. 15	本次共检电力变压器7台，7台电力变压器所检项目合格	
139	GX-B1312/20-1-25249~25253	2025. 5. 15	本次共检电力变压器5台，5台电力变压器所检项目合格	
140	GX-B1329/21-1-25047~25052	2025. 5. 15	本次共检氧化锌避雷器6组，6组氧化锌避雷器所检项目合格	

141	GX-B1312/20-1-25275~25288	2025. 5. 16	<p>本次共检电力变压器 14台，14台电力变压器所检 项目合格</p>	
142	GX-B1312/20-1-25289~25304	2025. 5. 16	<p>本次共检电力变压器 16台，16台电力变压器所检 项目合格</p>	
143	GX-B1598/24-1-25023	2025. 5. 16	<p>实测钢丝绳有效截面积损 失百分比最大为1.34%，小 于5%为正常</p>	

144	GX-B1598/24-1-25024	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常	 2025/04/28
145	GX-B1304/21-1-25004	2025. 5. 16	综合判定：合格	 2025-04-11
146	GX-B1598/24-1-25017	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为0.42%，小于5%为正常	 2025/4/11

147	GX-B1598/24-1-25018	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为0.81%，小于5%为正常	
148	GX-B1598/24-1-25019	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为0.48%，小于5%为正常	
149	GX-B1598/24-1-25020	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为0.75%，小于5%为正常	

150	GX-B1598/24-1-25021	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常	
151	GX-B1598/24-1-25022	2025. 5. 16	实测钢丝绳有效截面积损失百分比最大为0.75%，小于5%为正常	
152	GX-B1309/21-1-25019	2025. 5. 16	所检项目合格	

153	GX-B1500/21-1-25073	2025. 5. 16	综合判定：合格		
154	GX-B1500/21-1-25074	2025. 5. 16	综合判定：合格		
155	GX-B1500/21-1-25075	2025. 5. 16	综合判定：合格		

156	GX-B1309/21-1-25018	2025. 5. 16	所检项目合格		
157	GX-B1500/21-1-25070	2025. 5. 16	综合判定：合格		
158	GX-B1500/21-1-25071	2025. 5. 16	综合判定：合格		

159	GX-B1500/21-1-25072	2025. 5. 16	综合判定：合格		
160	GX-B1500/21-1-25067	2025. 5. 16	综合判定：合格		
161	GX-B1500/21-1-25068	2025. 5. 16	综合判定：合格		

162	GX-B1500/21-1-25069	2025. 5. 16	综合判定：合格	
163	GX-B1319/21-1-25011~25012	2025. 5. 16	<p>本次共检高压交流断路器2台，2台高压交流断路器所检项目合格</p>	
164	GX-B1322/21-1-25195~25198	2025. 5. 16	<p>本次共检验电力电缆4条，4条所检项目合格</p>	

165	GX-B1321/20-1-25507~25511	2025. 5. 19	本次共检电力电缆5条，5条电力电缆所检项目合格	
166	GX-B1321/20-1-25512~25516	2025. 5. 19	本次共检电力电缆5条，5条电力电缆所检项目合格	
167	GX-B1321/20-1-25517~25525	2025. 5. 19	本次共检电力电缆9条，9条电力电缆所检项目合格	

168	GX-B1321/20-1-25526~25529	2025. 5. 19	本次共检电力电缆4条，4条电力电缆所检项目合格	
169	GX-B1321/20-1-25530~25534	2025. 5. 19	本次共检电力电缆5条，5条电力电缆所检项目合格	
170	GX-B1321/20-1-25535~25541	2025. 5. 19	本次共检电力电缆7条，7条电力电缆所检项目合格	

171	GX-B1321/20-1-25542~25546	2025. 5. 19	本次共检电力电缆5条，5条电力电缆所检项目合格	
172	GX-B1321/20-1-25547~25555	2025. 5. 19	本次共检电力电缆9条，9条电力电缆所检项目合格	

173	GX-B1321/20-1-25556~25562	2025. 5. 19	本次共检电力电缆7条，7条电力电缆所检项目合格	 A photograph showing several workers in blue and grey uniforms and hard hats working in a confined space, likely a cable tunnel or manhole. They are surrounded by orange-painted metal structures and various cables. One worker in the foreground is kneeling and looking at a device. A yellow toolbox is on the floor. A timestamp '2025.5.19' is visible in the bottom right corner of the photo.
174	GX-B1321/20-1-25563~25567	2025. 5. 19	本次共检电力电缆5条，5条电力电缆所检项目合格	 A photograph of a worker in a grey uniform and red hard hat standing in a room with electrical equipment. The worker is holding a tool or device. In the background, there is a red piece of equipment and a metal railing with a white sign that reads '高压 危险' (High Voltage Danger) with a warning symbol. A timestamp '2025.3.27' is visible in the bottom right corner of the photo.

175	GX-B1321/20-1-25568~25577	2025. 5. 19	本次共检电力电缆10条，10条电力电缆所检项目合格	
176	GX-B1321/20-1-25578~25586	2025. 5. 19	本次共检电力电缆9条，9条电力电缆所检项目合格	