

序号	报告编号	发布日期	结论	影像资料
84	GX-B1301/23-3-25001	2025. 5. 12	综合判定:合格。	
85	GX-B1301/23-3-25002	2025. 5. 13	综合判定:合格。	

86	GX-B1323/21-3-25241~25250	2025年5月13日	所检项目合格。	
87	GX-B1301/23-3-25003	2025. 5. 14	综合判定:合格。	
88	GX-B1308/23-3-25017	2025年5月14日	综合判定:合格。	

89	GX-B1308/23-3-25018	2025年5月14日	所检项目合格。	
90	GX-B1312/20-3-25392~25393	2025. 5. 14	本次共检防爆干式变压器2台，2台防爆干式变压器所检项目合格。	
91	GX-B1328/20-3-25075	2025年5月14日	本次共检绝缘手套32只，32只绝缘手套合格。	



92	GX-B1328/20-3-25076	2025年5月14日	本次共检绝缘靴30只， 30只绝缘靴合格。	
93	GX-B1328/20-3-25077	2025年5月14日	本次共检验电器15支， 15支验电器合格。	
94	GX-B1328/20-3-25078	2025年5月14日	本次共检绝缘手套 36只，36只绝缘手套合 格。	

95	GX-B1328/20-3-25079	2025年5月14日	本次共检绝缘靴36只，36只绝缘靴合格。	
96	GX-B1328/20-3-25080	2025年5月14日	本次共检便携式接地和接地短路装置10套，10套便携式接地和接地短路装置所检项目合格。	
97	GX-B1328/20-3-25081	2025年5月14日	本次共检高压验电器10支，10支高压验电器所检项目合格。	

98	GX-B1328/20-3-25082	2025年5月14日	本次共检绝缘杆10套， 10套绝缘杆合格。	
99	GX-B1620/24-3-25026	2025年5月14日	实测流量26.7m ³ /h，不 做判定，其余所检项目 合格。	
100	GX-B1620/24-3-25027	2025年5月14日	实测流量27.1m ³ /h，不 做判定，其余所检项目 合格。	


101	GX-B1620/24-3-25028	2025年5月14日	实测流量25.4m ³ /h，不做判定，其余所检项目合格。	
102	GX-B1620/24-3-25029	2025年5月14日	实测流量10.6m ³ /h，不做判定，其余所检项目合格。	
103	GX-B1620/24-3-25030	2025年5月14日	实测流量25.0m ³ /h，不做判定，其余所检项目合格。	

104	GX-B1620/24-3-25031	2025年5月14日	实测流量24.0m ³ /h，不做判定，其余所检项目合格。	
105	GX-B1620/24-3-25032	2025年5月14日	实测流量65.4m ³ /h，不做判定，其余所检项目合格。	
106	GX-B1620/24-3-25033	2025年5月14日	实测流量13.5m ³ /h，不做判定，其余所检项目合格。	

107	GX-B1620/24-3-25012	2025年5月14日	实测流量645.1m ³ /h、电机输入功率254.2kW，不做判定，其余所检项目合格。	
108	GX-B1620/24-3-25013	2025年5月14日	实测流量657.3m ³ /h、电机输入功率257.5kW，不做判定，其余所检项目合格。	
109	GX-B1620/24-3-25014	2025年5月14日	实测流量622.1m ³ /h、电机输入功率248.7kW，不做判定，其余所检项目合格。	

110	GX-B1620/24-3-25010	2025年5月14日	实测流量1161.1m ³ /h、 电机输入功率 3560.2kW，不做判定， 其余所检项目合格。	
111	GX-B1620/24-3-25011	2025年5月14日	实测流量1168.6m ³ /h、 电机输入功率 3535.7kW，不做判定， 其余所检项目合格。	
112	GX-B1308/23-3-25019	2025年5月14日	综合判定：合格。	

113	GX-B1620/24-3-25034	2025年5月14日	实测流量10.1m ³ /h， 不做判定，其余所检项目合格。	
114	GX-B1620/24-3-25035	2025年5月14日	实测流量22.7m ³ /h， 不做判定，其余所检项目合格。	
115	GX-B1620/24-3-25036	2025年5月14日	实测流量25.3m ³ /h， 不做判定，其余所检项目合格。	

116	GX-B1620/24-3-25037	2025年5月14日	实测流量37.4m ³ /h，不做判定，其余所检项目合格。	
117	GX-B1620/24-3-25038	2025年5月14日	实测流量36.5m ³ /h，不做判定，其余所检项目合格。	
118	GX-B1620/24-3-25039	2025年5月14日	实测流量37.0m ³ /h，不做判定，其余所检项目合格。	


119	GX-B1620/24-3-25040	2025年5月14日	实测流量24.0m ³ /h，不做判定，其余所检项目合格。	
120	GX-B1620/24-3-25041	2025年5月14日	实测流量34.1m ³ /h，不做判定，其余所检项目合格。	
121	GX-B1620/24-3-25042	2025年5月14日	实测流量20.8m ³ /h，不做判定，其余所检项目合格。	

122	GX-B1321/20-3-251052~251062	2025年5月15日	本次共检电力电缆11条，11条电力电缆所检项目合格。	
123	GX-B1350/21-3-25005	2025年5月15日	所检项目合格。	
124	GX-B1620/24-3-25043	2025年5月15日	实测流量22.6m ³ /h，不做判定，其余所检项目合格。	

125	GX-B1620/24-3-25044	2025年5月15日	实测流量25.3m ³ /h, 不做判定, 其余所检项目合格。	
126	GX-B1620/24-3-25045	2025年5月15日	实测流量24.1m ³ /h, 不做判定, 其余所检项目合格。	
127	GX-B1620/24-3-25046	2025年5月15日	实测流量24.9m ³ /h, 不做判定, 其余所检项目合格。	


128	GX-B1620/24-3-25047	2025年5月15日	实测流量10.4m ³ /h, 不做判定, 其余所检项目合格。	
129	GX-B1620/24-3-25048	2025年5月15日	实测流量23.4m ³ /h, 不做判定, 其余所检项目合格。	
130	GX-B1620/24-3-25049	2025年5月15日	实测流量11.6m ³ /h, 不做判定, 其余所检项目合格。	


131	GX-B1620/24-3-25050	2025年5月15日	实测流量36.4m ³ /h， 不做判定，其余所检项目合格。	
132	GX-B1620/24-3-25051	2025年5月15日	实测流量9.4m ³ /h， 不做判定，其余所检项目合格。	
133	GX-B1620/24-3-25052	2025年5月15日	实测流量36.4m ³ /h， 不做判定，其余所检项目合格。	

134	GX-B1620/24-3-25053	2025年5月15日	实测流量20.7m ³ /h, 不做判定, 其余所检项目合格。	
135	GX-B1620/24-3-25054	2025年5月15日	实测流量33.3m ³ /h, 不做判定, 其余所检项目合格。	
136	GX-B1620/24-3-25055	2025年5月15日	实测流量31.6m ³ /h, 不做判定, 其余所检项目合格。	

137	GX-B1620/24-3-25056	2025年5月15日	实测流量19.0m ³ /h， 不做判定，其余所检项目合格。	
138	GX-B1564/21-3-25001	2025年5月15日	所检项目合格。	
139	GX-B1564/21-3-25002	2025年5月15日	所检项目合格。	

140	GX-B1564/21-3-25003	2025年5月15日	所检项目合格。	
141	GX-B1564/21-3-25004	2025年5月15日	所检项目合格。	
142	GX-B1564/21-3-25005	2025年5月15日	所检项目合格。	

143	GX-B1564/21-3-25006	2025年5月15日	所检项目合格。	
144	GX-B1564/21-3-25007	2025年5月15日	所检项目合格。	
145	GX-B1564/21-3-25008	2025年5月15日	所检项目合格。	

146	GX-B1564/21-3-25009	2025年5月15日	所检项目合格。	
147	GX-B1312/20-3-25394~25395	2025. 5. 15	本次共检防爆干式变压器2台，2台防爆干式变压器所检项目合格。	
148	GX-B1323/21-3-25220~25222	2025. 5. 16	所检项目合格。	

149	GX-B1323/21-3-25223~25226	2025. 5. 16	所检项目合格。	
150	GX-B1323/21-3-25227~25233	2025. 5. 16	所检项目合格。	
151	GX-B1620/24-3-25078	2025年5月18日	实测流量25.1m ³ /h, 不做判定, 其余所检项目合格。	

152	GX-B1620/24-3-25079	2025年5月18日	实测流量23.5m ³ /h, 不做判定, 其余所检项目合格。	
153	GX-B1620/24-3-25080	2025年5月18日	实测流量24.9m ³ /h, 不做判定, 其余所检项目合格。	
154	GX-B1620/24-3-25081	2025年5月18日	实测流量25.0m ³ /h, 不做判定, 其余所检项目合格。	

155	GX-B1620/24-3-25082	2025年5月18日	实测流量39.9m ³ /h，不做判定，其余所检项目合格。	
156	GX-B1620/24-3-25083	2025年5月18日	实测流量38.8m ³ /h，不做判定，其余所检项目合格。	
157	GX-B1620/24-3-25084	2025年5月18日	实测流量39.0m ³ /h，不做判定，其余所检项目合格。	

158	GX-B1620/24-3-25085	2025年5月18日	实测流量24.6m ³ /h, 不做判定, 其余所检项目合格。	
159	GX-B1620/24-3-25086	2025年5月18日	实测流量25.6m ³ /h, 不做判定, 其余所检项目合格。	
160	GX-B1620/24-3-25087	2025年5月18日	实测流量24.7m ³ /h, 不做判定, 其余所检项目合格。	

161	GX-B1620/24-3-25088	2025年5月18日	实测流量509.6m ³ /h， 不做判定，其余所检项目合格。	
162	GX-B1620/24-3-25089	2025年5月18日	实测流量515.3m ³ /h， 不做判定，其余所检项目合格。	
163	GX-B1620/24-3-25090	2025年5月18日	实测流量505.8m ³ /h， 不做判定，其余所检项目合格。	

164	GX-B1620/24-3-25091	2025年5月18日	实测流量499.0m ³ /h, 不做判定, 其余所检项目合格。	
165	GX-B1620/24-3-25092	2025年5月18日	实测流量236.8m ³ /h, 不做判定, 其余所检项目合格。	
166	GX-B1620/24-3-25093	2025年5月18日	实测流量220.5m ³ /h, 不做判定, 其余所检项目合格。	


167	GX-B1321/20-3-25910~25914	2025. 5. 16	本次共检电力电缆5条， 5条电力电缆所检项目合格。	 A photograph showing several workers in orange safety gear and hard hats inspecting power cables in a narrow tunnel. The workers are using flashlights to illuminate the cables. A timestamp in the bottom right corner reads "2025.03.25 11:24".
168	GX-B1321/20-3-25915~25920	2025. 5. 16	本次共检电力电缆6条， 6条电力电缆所检项目合格。	 A photograph of a worker in an orange safety suit and hard hat inspecting power cables. The worker is holding a flashlight and looking at the cables. A timestamp in the bottom right corner reads "2025.04.26 11:25".
169	GX-B1321/20-3-25921~25929	2025. 5. 16	本次共检电力电缆9条， 9条电力电缆所检项目合格。	 A photograph showing workers in orange safety gear inspecting power cables in a tunnel. The workers are using flashlights. A timestamp in the bottom right corner reads "2025.04.26 11:25".

170	GX-B1310/21-3-25050	2025年5月19日	符合标准要求。	
171	GX-B1323/21-3-25047~25048	2025年5月16日	所检项目合格。	
172	GX-B1620/24-3-25070	2025年5月18日	实测流量33.4m ³ /h，不做判定，其余所检项目合格。	

173	GX-B1620/24-3-25071	2025年5月18日	实测流量28.6m ³ /h，不做判定，其余所检项目合格。	
174	GX-B1620/24-3-25072	2025年5月18日	实测流量30.2m ³ /h，不做判定，其余所检项目合格。	
175	GX-B1620/24-3-25073	2025年5月18日	实测流量19.6m ³ /h，不做判定，其余所检项目合格。	

176	GX-B1620/24-3-25074	2025年5月18日	实测流量115.4m ³ /h， 不做判定，其余所检项目合格。	
177	GX-B1620/24-3-25075	2025年5月18日	实测流量62.9m ³ /h， 不做判定，其余所检项目合格。	
178	GX-B1620/24-3-25076	2025年5月18日	实测流量132.2m ³ /h， 不做判定，其余所检项目合格。	

179	GX-B1620/24-3-25077	2025年5月18日	实测流量154.7m ³ /h， 不做判定，其余所检项目合格。	
180	GX-B1310/21-3-25051	2025年5月19日	符合标准要求。	
181	GX-B1310/21-3-25052	2025年5月19日	未发现超过Φ2mm当量直径的缺陷。	

182	GX-B1428/21-3-25018	2025年5月19日	无缺陷痕迹显示。	
183	GX-B1310/21-3-25055	2025年5月19日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
184	GX-B1428/21-3-25019	2025年5月19日	无缺陷痕迹显示。	

185	GX-B1310/21-3-25054	2025年5月19日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 <p>2025.03.18</p>
186	GX-B1310/21-3-25053	2025年5月19日	符合标准要求。	 <p>2025.03.18</p>
187	GX-B1306/23-3-25001	2025年5月18日	所检项目合格。	 <p>2025.04.30</p>

188	GX-B1306/23-3-25002	2025年5月18日	所检项目合格。	
189	GX-B1306/23-3-25003	2025年5月18日	所检项目合格。	
190	GX-B1306/23-3-25004	2025年5月18日	所检项目合格。	

191	GX-B1306/23-3-25005	2025年5月18日	所检项目合格。	
192	GX-B1306/23-3-25006	2025年5月18日	所检项目合格。	
193	GX-B1306/23-3-25007	2025年5月18日	所检项目合格。	

194	GX-B1306/23-3-25008	2025年5月18日	所检项目合格。	
-----	---------------------	------------	---------	---