

序号	报告编号	发布日期	结论	影像资料
32	GX-B1361/22-A-25533	2025/5/8	所检项目合格	
33	GX-B1361/22-A-25534	2025/5/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1361/22-A-25524	2025/5/9	所检项目合格	 A photograph showing a worker in a light-colored uniform and gloves working on a workpiece in a workshop. The worker is using a tool to adjust or measure the workpiece. In the background, another worker is visible near a large machine. A yellow date stamp '2025/5/5' is visible in the bottom right corner of the image.
35	GX-B1361/22-A-25525	2025/5/9	所检项目合格	 A photograph showing two workers in a workshop. One worker is operating a large machine, while the other is standing nearby, possibly assisting or observing. The workers are wearing light-colored uniforms. A yellow date stamp '2025/5/5' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
36	GX-B1361/22-A-25526	2025/5/9	所检项目合格		
37	GX-B1361/22-A-25520	2025/5/12	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
38	GX-B1361/22-A-25521	2025/5/12	所检项目合格	 A photograph showing a worker in a light-colored uniform operating a lathe machine in a workshop. The worker is focused on the task, and the machine is in operation. A date stamp '2024/5/16' is visible in the bottom right corner of the image.
39	GX-B1361/22-A-25522	2025/5/12	所检项目合格	 A photograph showing a worker in a light-colored uniform operating a lathe machine in a workshop. The worker is focused on the task, and the machine is in operation. A date stamp '2024/5/17' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
40	GX-B1361/22-A-25523	2025/5/12	所检项目合格	
41	GX-B1362/23-A-25159	2025/5/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1362/23-A-25160	2025/5/12	所检项目合格	
43	GX-B1361/22-A-25527	2025/5/9	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1361/22-A-25528	2025/5/9	所检项目合格	
45	GX-B1361/22-A-25529	2025/5/9	合格	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1361/22-A-25532	2025/5/9	合格	 A photograph showing two men in light-colored work shirts operating a large industrial machine in a workshop. The machine has a control panel on the left. The man on the right is wearing gloves and appears to be adjusting or inspecting a component on the machine. The background shows a typical workshop environment with various tools and equipment. A yellow timestamp '2025/5/6' is visible in the bottom right corner of the image.
47	GX-B1362/23-A-25164	2025/5/13	合格	 A photograph showing two men in light-colored work shirts operating a large industrial machine in a workshop. The machine has a control panel on the left. The man on the right is wearing gloves and appears to be adjusting or inspecting a component on the machine. The background shows a typical workshop environment with various tools and equipment. A yellow timestamp '2025/5/7' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
48	GX-B1362/23-A-25171	2025/5/13	所检项目合格	
49	GX-B1361/22-A-25535	2025/5/13	合格	

序号	报告编号	发布日期	结论	影像资料	
50	GX-B1361/22-A-25544	2025/5/13	所检项目合格		
51	GX-B1361/22-A-25545	2025/5/13	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
52	GX-B1361/22-A-25547	2025/5/13	合格	 A photograph showing two workers in a workshop. They are standing next to a large industrial machine, possibly a lathe or mill. One worker is operating the machine while the other is observing. The date '2025/5/12' is visible in the bottom right corner of the image.
53	GX-B1362/23-A-25176	2025/5/15	不合格	 A photograph showing two workers in a workshop, similar to the one above. They are operating a large industrial machine. The date '2025/5/13' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
54	GX-B1362/23-A-25177	2025/5/15	合格	
55	GX-B1361/22-A-25496	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
56	GX-B1361/22-A-25497	2025/5/15	所检项目合格	
57	GX-B1361/22-A-25498	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1361/22-A-25499	2025/5/15	所检项目合格	
59	GX-B1361/22-A-25500	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
60	GX-B1361/22-A-25501	2025/5/15	所检项目合格	
61	GX-B1361/22-A-25502	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
62	GX-B1361/22-A-25503	2025/5/15	所检项目合格		
63	GX-B1361/22-A-25504	2025/5/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
64	GX-B1361/22-A-25505	2025/5/15	所检项目合格	
65	GX-B1361/22-A-25506	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
66	GX-B1361/22-A-25507	2025/5/15	所检项目合格		
67	GX-B1361/22-A-25508	2025/5/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
68	GX-B1361/22-A-25509	2025/5/15	所检项目合格		
69	GX-B1361/22-A-25510	2025/5/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
70	GX-B1361/22-A-25511	2025/5/15	所检项目合格	
71	GX-B1361/22-A-25512	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1361/22-A-25513	2025/5/15	所检项目合格	
73	GX-B1361/22-A-25514	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
74	GX-B1361/22-A-25515	2025/5/15	所检项目合格		
75	GX-B1361/22-A-25516	2025/5/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
76	GX-B1361/22-A-25517	2025/5/15	所检项目合格	
77	GX-B1361/22-A-25518	2025/5/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
78	GX-B1361/22-A-25519	2025/5/15	所检项目合格	