


序号	报告编号	发布日期	结论	影像资料
98	GX-B1310/21-5-25116	2025/5/16	符合标准要求。	
99	GX-B1310/21-5-25117	2025/5/16	符合标准要求。	

100	GX-B1310/21-5-25100	2025/5/19	符合标准要求。	
101	GX-B1310/21-5-25101	2025/5/19	符合标准要求。	

102	GX-B1310/21-5-25102	2025/5/19	符合标准要求。	
103	GX-B1495/20-5-25692-25707	2025. 5. 16	本次共检高压开关柜16台，16台高压开关柜所检项目合格。	

104	GX-B1495/20-5-25630-25649	2025. 5. 16	本次共检高压开关柜20台，20台高压开关柜所检项目合格。	
105	GX-B1495/20-5-25651-25677	2025. 5. 16	本次共检高压开关柜27台，27台高压开关柜所检项目合格。	

106	GX-B1495/20-5-25742-25755	2025. 5. 16	本次共检高压开关柜14台，14台高压开关柜所检项目合格。	
107	GX-B1495/20-5-25721-25741	2025. 5. 16	本次共检高压开关柜21台，21台高压开关柜所检项目合格。	

108	GX-B1495/20-5-25553～25560	2025年5月19日	本次共检防爆型高压配电装置8台，8台防爆型高压配电装置所检项目合格。 。	 2025年4月5日
109	GX-B1495/20-5-25561～25577	2025年5月19日	本次共检防爆型高压配电装置17台，17台防爆型高压配电装置所检项目合格。	 2025年4月6日

110	GX-B1495/20-5-25578~25597	2025年5月19日	本次共检高压开关柜20台，20台高压开关柜所检项目合格。	
111	GX-B1495/20-5-25598~25611	2025年5月20日	本次共检高压开关柜14台，14台高压开关柜所检项目合格。	

112	GX-B1495/20-5-25612~25620	2025年5月20日	本次共检防爆型高压配电装置9台，9台防爆型高压配电装置所检项目合格。 。	
113	GX-B1495/20-5-25621~25629	2025年5月20日	本次共检防爆型高压配电装置9台，9台防爆型高压配电装置所检项目合格。 。	

114	GX-B1310/21-5-25112	2025. 5. 22	符合标准要求。		
115	GX-B1310/21-5-25113	2025. 5. 22	符合标准要求。		

116	GX-B1495/20-5-25791~25807	2025. 5. 22	本次共检高压开关柜17台，17台高压开关柜所检项目合格。	
117	GX-B1495/20-5-25808~25825	2025. 5. 22	本次共检高压开关柜18台，18台高压开关柜所检项目合格。	

118	GX-B1495/20-5-25826~25837	2025. 5. 23	本次共检防爆型高压配电装置12台，12台防爆型高压配电装置所检项目合格。	
119	GX-B1309/21-5-25001	2025. 5. 22	所检项目合格。	

120	GX-B1500/21-5-25001	2025. 5. 22	综合判定：合格。	 A worker wearing a blue uniform, a red helmet, and black boots is operating a blue industrial machine. The machine has a large cylindrical component. The worker is standing on a wooden platform. The background shows a concrete wall and some equipment. A red date stamp '2025/05/07' is visible in the bottom right corner of the image.
121	GX-B1500/21-5-25002	2025. 5. 22	综合判定：合格。	 A worker wearing a blue uniform, a red helmet, and black boots is operating a blue industrial machine. The machine has a large cylindrical component. The worker is standing on a wooden platform. The background shows a concrete wall and some equipment. A red date stamp '2025/05/07' is visible in the bottom right corner of the image.

122	GX-B1500/21-5-25003	2025. 5. 22	综合判定：合格。	
123	GX-B1500/21-5-25004	2025. 5. 22	综合判定：合格。	

124	GX-B1309/21-5-25002	2025. 5. 22	所检项目合格。	
125	GX-B1500/21-5-25005	2025. 5. 22	综合判定：合格。	

126	GX-B1500/21-5-25006	2025. 5. 22	综合判定：合格。	 A worker in a blue uniform and red helmet is kneeling and adjusting a blue industrial machine. A yellow timestamp '2025/5/7' is visible in the bottom right corner of the photo.
127	GX-B1500/21-5-25007	2025. 5. 22	综合判定：合格。	 A worker in a blue uniform and red helmet is kneeling and working on a large industrial component. A yellow timestamp '2025/5/7' is visible in the bottom right corner of the photo.

128	GX-B1500/21-5-25008	2025. 5. 22	综合判定：合格。			
129	GX-B1309/21-5-25003	2025. 5. 22	所检项目合格。			

130	GX-B1500/21-5-25009	2025. 5. 22	综合判定：合格。	 A worker in a blue uniform and red helmet is inspecting a blue industrial machine. The machine has a yellow safety rail. The date 2025/5/8 is visible in the bottom right corner of the photo.
131	GX-B1500/21-5-25010	2025. 5. 22	综合判定：合格。	 A worker in a blue uniform and red helmet is working on a blue industrial machine. The machine has a yellow safety rail. The date 2025/5/8 is visible in the bottom right corner of the photo.

132	GX-B1500/21-5-25011	2025. 5. 22	综合判定：合格。		
133	GX-B1500/21-5-25012	2025. 5. 22	综合判定：合格。		

134	GX-B1309/21-5-25004	2025. 5. 22	所检项目合格。		
135	GX-B1500/21-5-25013	2025. 5. 22	综合判定：合格。		

136	GX-B1500/21-5-25014	2025. 5. 22	综合判定：合格。	
137	GX-B1500/21-5-25015	2025. 5. 22	综合判定：合格。	

138	GX-B1500/21-5-25016	2025. 5. 22	综合判定：合格。	
139	GX-B1309/21-5-25005	2025. 5. 23	所检项目合格。	

140	GX-B1500/21-5-25017	2025. 5. 23	综合判定：合格。	
141	GX-B1500/21-5-25018	2025. 5. 23	综合判定：合格。	

142	GX-B1500/21-5-25019	2025. 5. 23	综合判定：合格。	
143	GX-B1500/21-5-25020	2025. 5. 23	综合判定：合格。	

144	GX-B1309/21-5-25006	2025. 5. 23	所检项目合格。		
145	GX-B1500/21-5-25021	2025. 5. 23	综合判定：合格。		

146	GX-B1500/21-5-25022	2025. 5. 23	综合判定：合格。	
147	GX-B1500/21-5-25023	2025. 5. 23	综合判定：合格。	

148	GX-B1500/21-5-25024	2025. 5. 23	综合判定：合格。	
149	GX-B1500/21-5-25025	2025. 5. 23	综合判定：合格。	

150	GX-B1309/21-5-25007	2025. 5. 23	所检项目合格。		
151	GX-B1500/21-5-25026	2025. 5. 23	综合判定：合格。		

152	GX-B1500/21-5-25027	2025. 5. 23	综合判定：合格。	
153	GX-B1500/21-5-25028	2025. 5. 23	综合判定：合格。	

154	GX-B1500/21-5-25029	2025. 5. 23	综合判定：合格。	
155	GX-B1500/21-5-25030	2025. 5. 23	综合判定：合格。	

156	GX-B1314/21-5-25007~25009	2025年5月23日	本次共检干式电抗器3台，3台干式电抗器所检项目合格。	 2025年4月6日
157	GX-B1310/21-5-25118	2025/5/23	符合标准要求。	

158	GX-B1310/21-5-25119	2025/5/23	符合标准要求。	
159	GX-B1310/21-5-25120	2025/5/23	符合标准要求。	

160	GX-B1310/21-5-25121	2025/5/23	符合标准要求。	
161	GX-B1312/20-5-25187~25191	2025. 5. 23	本次共检电力变压器5台，5台电力变压器所检项目合格。 。	

162	GX-B1312/20-5-25185~25186	2025. 5. 23	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
163	GX-B1312/20-5-25192~25199	2025. 5. 23	本次共检电力变压器8台，8台电力变压器所检项目合格。 。	

164	GX-B1312/20-5-25200~25208	2025. 5. 23	本次共检电力变压器9台，9台电力变压器所检项目合格。 。	
165	GX-B1312/20-5-25209~25212	2025. 5. 23	本次共检电力变压器4台，4台电力变压器所检项目合格。 。	

166	GX-B1312/20-5-25213~25220	2025. 5. 23	本次共检电力变压器8台，8台电力变压器所检项目合格。 。	
167	GX-B1328/20-5-25101	2025年5月23日	本次共检绝缘手套4只，4只绝缘手套合格。	

168	GX-B1328/20-5-25102	2025年5月23日	本次共检绝缘靴2只，2只绝缘靴合格。	
169	GX-B1328/20-5-25103	2025年5月23日	本次共检绝缘手套4只，4只绝缘手套合格。	

170	GX-B1328/20-5-25104	2025年5月23日	本次共检绝缘靴2只，2只绝缘靴合格。	
-----	---------------------	------------	--------------------	---