


序号	报告编号	发布日期	结论	影像资料
180	GX-B1517/20-2-25001	2025/5/10	综合判定：合格。	
181	GX-B1517/20-2-25002	2025/5/10	综合判定：合格。	
182	GX-B1312/20-2-25047	2025/5/10	所检项目合格。	

183	GX-B1329/21-2-25158~25159	2025.05.23	本次共检氧化锌避雷器2组, 2组所检项目合格。 。	
184	GX-B1313/21-2-25195~25196	2025.05.26	本次共检电力变压器2台, 2台电力变压器所检项目合格。	
185	GX-B1352/21-2-25086~25103	2025/5/15	本次共检矿用防爆低压交流真空馈电开关18台, 18台所检项目合格。	

186	GX-B1352/21-2-25104~25125	2025/5/15	本次共检矿用防爆低压交流真空馈电开关22台,22台所检项目合格。			
187	GX-B1359/21-2-25012~25018	2025/5/15	本次共检矿用隔爆型照明信号综合保护装置7台,7台所检项目合格。			
188	GX-B1359/21-2-25019~25022	2025/5/15	本次共检矿用隔爆型照明信号综合保护装置4台,4台所检项目合格。			

189	GX-B1359/21-2-25023~25034	2025/5/15	本次共检矿用隔爆型照明信号综合保护装置12台, 12台所检项目合格。			
190	GX-B1354/20-2-25001~25001	2025/5/26	电网接地电容电流符合规定。			
191	GX-B1350/21-2-25023	2025/5/13	本次共检验接地装置7处, 7处接地装置所检项目合格。			

192	GX-B1350/21-2-25024	2025/5/13	本次共检验接地装置3处，3处接地装置所检项目合格。	 2025/04/22
193	GX-B1350/21-2-25025	2025/5/13	本次共检验接地装置9处，9处接地装置所检项目合格。	 2025/04/23
194	GX-B1309/21-2-25017	2025.05.28	所检项目合格。	 2025.5.12

195	GX-B1500/21-2-25068	2025.05.28	综合判定：合格。	
196	GX-B1500/21-2-25069	2025.05.28	综合判定：合格。	
197	GX-B1500/21-2-25070	2025.05.28	综合判定：合格。	

198	GX-B1500/21-2-25071	2025.05.28	综合判定：合格。		
199	GX-B1500/21-2-25072	2025.05.28	综合判定：合格。		
200	GX-B1500/21-2-25073	2025.05.28	综合判定：合格。		

201	GX-B1500/21-2-25074	2025.05.28	综合判定：合格。	
202	GX-B1329/21-2-25122~25125	2025.05.28	本次共检氧化锌避雷器4组，4组所检项目合格。 。	
203	GX-B1329/21-2-25126~25128	2025.05.28	本次共检氧化锌避雷器3组，3组所检项目合格。 。	


204	GX-B1329/21-2-25129~25135	2025.05.28	本次共检氧化锌避雷器7组，7组所检项目合格。	
205	GX-B1324/21-2-25027~25028	2025.05.29	所检项目合格。	
206	GX-B1324/21-2-25029~25030	2025.05.29	所检项目合格。	

207	GX-B1324/21-2-25031~25032	2025.05.29	所检项目合格。	 A photograph showing two workers in safety gear (hard hats and work clothes) standing in a room, inspecting or working on a piece of equipment. The date stamp in the bottom right corner of the photo is 2025/04/30.
208	GX-B1322/21-2-25323~25325	2025.05.29	本次共检验电力电缆3条，3条电力电缆所检项目合格。	 A photograph showing a worker in safety gear inspecting a long, narrow corridor or tunnel. The date stamp in the bottom right corner of the photo is 2025/04/24.
209	GX-B1322/21-2-25326	2025.05.29	所检项目合格。	 A photograph showing a worker in safety gear inspecting equipment in a dark environment, possibly a tunnel or confined space. The date stamp in the bottom right corner of the photo is 2025/04/24.

210	GX-B1322/21-2-25327~25333	2025.05.29	本次共检验电力电缆7条，7条电力电缆所检项目合格。	 A worker wearing a red helmet and a grey uniform is working on a cable in a confined space. The worker is holding a tool and looking towards the camera. The date 2025/04/25 is visible in the bottom right corner of the image.
211	GX-B1322/21-2-25334~25336	2025.05.29	本次共检验电力电缆3条，3条电力电缆所检项目合格。	 A worker wearing a red helmet and a grey uniform is working on a cable in a confined space. The worker is kneeling and using a tool. The date 2025/04/26 is visible in the bottom right corner of the image.
212	GX-B1322/21-2-25337~25340	2025.05.29	本次共检验电力电缆4条，4条电力电缆所检项目合格。	 A worker wearing a red helmet and a grey uniform is working on a cable in a confined space. The worker is kneeling and using a tool. The date 2025/04/28 is visible in the bottom right corner of the image.

213	GX-B1322/21-2-25341~25343	2025.05.29	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
214	GX-B1322/21-2-25344~25352	2025.05.29	本次共检验电力电缆9条，9条电力电缆所检项目合格。	
215	GX-B1322/21-2-25353~25358	2025.05.29	本次共检验电力电缆6条，6条电力电缆所检项目合格。	

216	GX-B1310/21-2-25082	2025.05.29	符合标准要求。	
217	GX-B1427/21-2-25082	2025.05.29	符合标准要求。	
218	GX-B1350/21-2-25028	2025/5/30	本次共检接地装置 15处，15处接地装置所 检项目合格。	

219	GX-B1310/21-2-25089	2025/5/30	符合标准要求。	 2025/05/21
220	GX-B1428/21-2-25089	2025/5/30	无缺陷迹痕显示。	 2025/05/21