

序号	报告编号	发布日期	结论	影像资料
1	GX-B1603/22-F-250196	2025.7.1	所检项目合格	
2	GX-B1602/22-F-25047	2025.7.1	所检项目合格	
3	GX-B1540/20-F-251649~251654	2025.7.3	所检项目合格	

4	GX-B1540/20-F-251655~251660	2025.7.3	所检项目合格	 A photograph showing two technicians in a laboratory. One technician, wearing a light blue shirt, is looking at a device. The other, wearing a grey shirt with '中国中检' (China Inspection and Certification Group) on the back, is working with equipment inside a fume hood. The date '2025/6/15' is visible in the bottom right corner of the photo.
5	GX-B1540/20-F-251661~251666	2025.7.3	所检项目合格	 A photograph showing two technicians in a laboratory. One technician, wearing a light blue shirt, is looking at a device. The other, wearing a grey shirt with '中国中检' (China Inspection and Certification Group) on the back, is working with equipment inside a fume hood. The date '2025/6/16' is visible in the bottom right corner of the photo.
6	GX-B1540/20-F-251667~251672	2025.7.3	所检项目合格	 A photograph showing two technicians in a laboratory. One technician, wearing a light blue shirt, is looking at a device. The other, wearing a grey shirt with '中国中检' (China Inspection and Certification Group) on the back, is working with equipment inside a fume hood. The date '2025/6/17' is visible in the bottom right corner of the photo.

7	GX-B1540/20-F-251673~251678	2025.7.3	所检项目合格	
8	GX-B1528/20-F-25134~25139	2025.7.4	所检项目合格	
9	GX-B1528/20-F-25140~25145	2025.7.4	所检项目合格	

10	GX-B1528/20-F-25146~25151	2025.7.4	所检项目合格	
11	GX-B1528/20-F-25152~25157	2025.7.4	所检项目合格	
12	GX-B1528/20-F-25158~25163	2025.7.4	所检项目合格	

13	GX-B1533/21-F-25001~25003	2025.7.3	所检项目合格	
----	---------------------------	----------	--------	---