

序号	报告编号	发布日期	结论	影像资料
2	GX-B1423/20-Z-25001	2025年11月14日	综合判定：合格	
3	GX-B1423/20-Z-25002	2025年11月14日	综合判定：合格	

4	GX-B1423/20-Z-25003	2025年11月14日	综合判定：合格	
5	GX-B1423/20-Z-25004	2025年11月14日	综合判定：合格	

6	GX-B1423/20-Z-25005	2025年11月14日	综合判定：合格	 A green MTHISON K-1233 dump truck is parked on a dirt surface. Two workers, one in a red jumpsuit and one in a white jumpsuit, are standing in front of the truck. The truck has "K-1233" and "MTHISON" written on its side. A yellow date stamp "2025/11/11" is visible in the bottom right corner of the image.
7	GX-B1423/20-Z-25006	2025年11月14日	综合判定：合格	 A green MTHISON K-1233 dump truck is parked on a dirt surface. Two workers, one in a red jumpsuit and one in a white jumpsuit, are standing in front of the truck. The truck has "K-1233" and "MTHISON" written on its side. A yellow date stamp "2025/11/11" is visible in the bottom right corner of the image.

8	GX-B1423/20-Z-25007	2025年11月14日	综合判定：合格	 A large green MTH150N K-1230 HEV dump truck is shown from a side-front angle. Two workers in safety gear stand in front of the truck. The truck has "MTH150N", "K-1230", and "HEV" markings. A yellow date stamp "2025/11/11" is in the bottom right corner.
9	GX-B1423/20-Z-25008	2025年11月14日	综合判定：合格	 A large green MTH150N K-1231 HEV dump truck is shown from a side-front angle. Two workers in safety gear stand in front of the truck. The truck has "MTH150N", "K-1231", and "HEV" markings. A yellow date stamp "2025/11/11" is in the bottom right corner.

10	GX-B1423/20-Z-25009	2025年11月14日	综合判定：合格	
11	GX-B1423/20-Z-25010	2025年11月14日	综合判定：合格	