

序号	报告编号	发布日期	结论	影像资料
1	GX-B1531/25-F-250978~250982	2025.12.1	所检项目合格	 2025/11/26
2	GX-B1568/22-F-25761~25778	2025.12.1	所检项目合格	 2025/11/18

3	GX-B1568/22-F-25739~25760	2025.12.1	本次共检验矿用风速表22台，22台所检项目合格。	
4	GX-B1540/20-F-253234~253258	2025.12.1	所检项目合格	

5	GX-B1374/22-F-251015~251016	2025.12.3	所检项目合格	
6	GX-B1540/20-F-253375~253384	2025.12.3	所检项目合格	

7	GX-B1372/22-F-252956~252962	2025.12.3	所检项目合格	 2025/11/14
8	GX-B1603/22-F-250385~250386	2025.12.3	所检项目合格	 2025/11/13

9	GX-B1540/20-F-258422~258436	2025.12.3	所检项目合格	 2025/11/15
10	GX-B1540/20-F-253397~2533421	2025.12.3	所检项目合格	 2025/11/15

11	GX-B1568/22-F-25728~25734	2025.12.3	所检项目合格	 2025/11/14
12	GX-B1603/22-F-250390~250391	2025.12.2	所检项目合格	 2025/11/26

13	GX-B1601/22-F-251027-251028	2025.12.5	所检项目合格	 2025.11.25
14	GX-B1601/22-F-251029~251030	2025.12.5	所检项目合格	 2025.11.25

15	GX-B1601/22-F-251031~251037	2025.12.4	所检项目合格	 A photograph showing two men in grey lab coats working in a laboratory. One man is seated at a desk with a computer monitor displaying a software interface with multiple windows. The other man is standing behind him, looking at a piece of equipment. The date "2025.11.25" is visible in the bottom right corner of the photo.
16	GX-B1410/22-F-25748~25752	2025.12.4	所检项目合格	 A photograph showing two men in grey lab coats working in a laboratory. They are standing next to a large, complex piece of laboratory equipment, possibly a gas chromatograph or similar analytical instrument, which has various tubes and a control panel. The date "2025.11.10" is visible in the bottom right corner of the photo.

17	GX-B1568/22-F-25788~25789	2025.12.5	所检项目合格	
18	GX-B1568/22-F-25790~25793	2025.12.5	所检项目合格	

19	GX-B1568/22-F-25797	2025.12.5	所检项目合格	
20	GX-B1595/22-F-25178~25179	2025.12.5	所检项目合格	

21	GX-B1602/22-F-25094	2025.12.5	所检项目合格	
22	GX-B1602/22-F-25092~25093	2025.12.5	所检项目合格	

23	GX-B1606/23-25569~25572	2025.12.5	所检项目合格	 2025.12.3
24	GX-B1605/23-F-25564~25567	2025.12.5	所检项目合格	 2025.12.3

25	GX-B1593/21-F-25523~25530	2025.12.4	所检项目合格	 2025/11/28
26	GX-B1593/21-F-25499~25507	2025.12.5	所检项目合格	 2025.11.11

27	GX-B1374/22-F-251026~251038	2025.12.5	所检项目合格	 A photograph showing two men in grey lab coats working in a laboratory. One man is leaning over a piece of equipment, possibly a vacuum system, while the other stands beside him, looking at a clipboard or document. They are positioned in front of a blue fume hood. The date '2025.11.17' is overlaid in the bottom right corner of the photo.
28	GX-B1374/22-F-250985~250999	2025.12.5	所检项目合格	 A photograph showing two men in grey lab coats working in a laboratory. One man is standing and holding a long probe or tool, while the other stands beside him, looking on. They are positioned in front of a blue fume hood. The date '2025.11.11' is overlaid in the bottom right corner of the photo.

29	GX-B1374/22-F-251000~251004	2025.12.5	所检项目合格	 <p>2025.11.11</p>
30	GX-B1570/22-F-25024	2025.12.5	<p>根据煤样升温氧化试验结果，采用煤最短自然发火期快速预测模型得煤样最短自然发火期为104天。</p>	

31	GX-B1540/20-F-253385~253387	2025.12.8	本次共检验多参数气体测定器3台，3台所检项目合格。	 2025.11.16
32	GX-B1529/20-F-25675~25677	2025.12.3	本次共检验多参数气体测定器3台，3台所检项目合格。	

33	GX-B1528/20-F-25941~25943	2025.12.3	本次共检验多参数气体测定器3台，3台所检项目合格。	 2025.11.16
34	GX-B1543/25-F-25267~25269	2025.12.4	本次共检验多参数气体测定器3台，3台所检项目合格。	 2025.11.16

35	GX-B1542/21-F- 25632~25649	2025.12.4	本次共检验光干涉式甲烷测定器18台，18台所检项目合格。	 2025.11.14
36	GX-B1529/20-F-25659~25674	2025.12.3	本次共检验一氧化碳测定器16台，16台所检项目合格。	 2025.11.15

37	GX-B1540/20-F-253437~253453	2025.12.8	本次共检验报警仪17台，17台所检项目合格。	
38	GX-B1540/20-F-253388~253396	2025.12.8	本次共检验报警仪9台，9台所检项目合格。	

39	GX-B1592/21-F-25180	2025.12.3	所检项目合格。	
40	GX-B1373/21-F-25572	2025.12.8	所检项目合格。	

41	GX-B1593/21-F-25508~25509	2025.12.3	本次共检验烟雾传感器2台，2台所检项目合格。	 2025.11.14
42	GX-B1374/22-F- 251013~251014	2025.12.3	本次共检验一氧化碳传感器2台，2台所检项目合格。	 2025.11.14

43	GX-B1601/22-F-251041~251046	2025.12.4	本次共检验矿用风速传感器6台，6台所检项目合格。	
----	-----------------------------	-----------	--------------------------	---